

Location Information			Upstream/System-Owned Portion (closest to source/water main)										Downstream/Customer-Owned Portion (closest to building plumbing)								Entire Service Line Material Classification (If error or "Missing Information" appears, ensure all required columns are filled correctly. See instructions)
Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	
1	5707 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
3	5716 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
4	5721 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
5	5724 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
6	5730 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
7	5735 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
8	5742 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
9	5743 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
10	5759 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
11	5767 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
12	5789 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
13	5790 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
14	5926 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
15	5934 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
16	5937 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
17	5944 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
18	5961 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
19	5976 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
20	5984 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
21	5989 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
22	5990 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
23	6079 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
24	6023 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
25	6050 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
26	6064 ANTHONY ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
27	6067 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
28	5960 A ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
31	25300 COLORADO		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
32	4990 LEEVE RD		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/15/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/15/2024		Non-lead
33	6040 LEVITI ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
34	6042 LEVITI ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
35	6044 LEVITI ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
36	6046 LEVITI ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
38	24615 MANNING AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-lead
39	24634 MANNING AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-lead
41	5770 S AMADOR AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-lead
42	5796 S AMADOR AVE		Unknown	Don't Know	Don't know	Unknown	1		No				Non-Lead - Plastic	Unknown	1		No				Lead Status Unknown
43	5860 S AMADOR AVE		Unknown	Don't Know	Don't know	Unknown	1		No				Unknown	Unknown	1		No				Lead Status Unknown
44	5880 S AMADOR AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-lead
45	5894 S AMADOR AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-lead
46	5906 S AMADOR AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-lead
47	5926 S AMADOR AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-lead
48	5354 S CALAVERAS AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	2/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	2/1/2024		Non-lead
49	5742 S CALAVERAS AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/26/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/26/2024		Non-lead
50	6160 S CALAVERAS AVE		Galvanized	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/26/2024		Galvanized	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/26/2024		Non-lead
51	6417 S CALAVERAS AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/26/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/26/2024		Non-lead
52	7121 S CALAVERAS AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
53	5815 A S CALAVERAS AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
56	8147 S CONTRA COSTA RD		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
57	8587 A S CONTRA COSTA RD		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	7/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	7/1/2024		Non-lead
58	8587 B S CONTRA COSTA RD		Non-Lead - Plastic	No	No	Unknown	3	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	3	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
59	5843 S DANIELS AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-lead
60	5846 S DANIELS AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-lead
61	5850 S DANIELS AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-lead
62	5856 S DANIELS AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/29/2024		Non-lead

Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (If error or "Missing Information" appears, ensure all required columns are filled correctly. See instructions)
124	5832 S JUANCHE ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
125	5835 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
126	5842 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
127	5863 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
128	5923 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
129	5929 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
130	5965 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
131	5975 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
132	5985 S JUANCHE ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
133	5992 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
134	5993 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
135	5994 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
136	6013 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
137	6019 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
138	6043 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
140	6063 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
141	6069 S JUANCHE ST		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
142	6081 S JUANCHE ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
143	6093 S JUANCHE ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
145	6033 B S JUANCHE ST		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
146	6052 B S JUANCHE ST		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-lead
147	6052A S JUANCHE ST		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-lead
148	7217 S MARIN RD		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
149	7246 S MARIN RD		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	2/5/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	2/5/2024		Non-lead
151	7444 S MARIN RD		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
152	9028 S NAPA AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
152A	9025 S NAPA AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-lead
153	6741 S SACRAMENTO AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
154	5726 S SCHOOL AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-lead
155	5769 S SCHOOL AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
156	5777 S SCHOOL AVE		Galvanized	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
157	5785 S SCHOOL AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
158	5809 S SCHOOL AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
159	5815 S SCHOOL AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
160	5825 S SCHOOL AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
161	5826 S SCHOOL AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
162	5866 S SCHOOL AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
163	5876 S SCHOOL AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
164	5884 S SCHOOL AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
165	5910 S SCHOOL AVE		Unknown	Don't Know	Don't know	Unknown	1		No				Unknown	Unknown	1		No				Lead Status Unknown
166	5926 S SCHOOL AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
167	5934 S SCHOOL AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
168	5944 S SCHOOL AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
169	5967 S SCHOOL AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
170	5977 S SCHOOL AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
171	5985 S SCHOOL AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead
172	6947 S TUOLUMNE AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
173	24774 W ADAMS AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
174	25025 W ADAMS AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
175	25671 W ADAMS AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
176	25944 W ADAMS AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
177	26881 W ADAMS AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
178	27843 W ADAMS AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Non-lead
179	25770 W AMERICAN AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/15/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	6/15/2024		Non-lead
180	27344 W CLAYTON AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	1/30/2024		Non-lead

Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (If error or "Missing Information" appears, ensure all required columns are filled correctly. See instructions)
353	25440A W WILLIAMS AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
354	25440B W WILLIAMS AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
355	25440C W WILLIAMS AVE		Galvanized	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Galvanized	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	1/31/2024		Non-lead
356	25411 W MORTON AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Non-lead
357	25382 W WILLIAMS AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
358	28285 W CLAYTON AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-lead
359	5810 ANTHONY ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	5/1/2024		Non-lead
360	5726 S JUANCHE ST		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-lead
361	S SCHOOL AVE		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	6/1/2024		Non-lead
362	James and Randolph		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	7/1/2024		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	7/1/2024		Non-lead
363	McKamey and Anthony		Non-Lead - Plastic	No	No	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	7/1/2024		Non-Lead - Plastic	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	7/1/2024		Non-lead
370	25869 W MORTON AVE		Non-Lead - Plastic	No	No	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Non-Lead - Plastic	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Non-lead
371	Woodshop		Unknown	Don't Know	Don't know	Unknown	2		No				Unknown	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Lead Status Unknown
372	Ag Farm		Unknown	Don't Know	Don't know	Unknown	3		No				Unknown	Unknown	3	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Lead Status Unknown
373	25321 W Silveria Ave		Unknown	Don't Know	Don't know	Unknown	1		No				Unknown	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Lead Status Unknown
374	5944 W Fairless		Unknown	Don't Know	Don't know	Unknown	1		No				Unknown	Unknown	1	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Lead Status Unknown
375	5989 Anthony		Unknown	Don't Know	Don't know	Unknown	2		No				Unknown	Unknown	2	Field inspection	Yes	Visual inspection at the meter pit	12/24/2025		Lead Status Unknown